







Updating the antenna location

The are no differences between the antenna, the same pattern, the only change is the position of the antenna.

PCB00368 Before	PCB00388 After
<p data-bbox="386 415 487 447">Top side</p>  <p data-bbox="110 772 430 804">The Antenna position(old).</p> 	<p data-bbox="1101 415 1201 447">Top side</p>  <p data-bbox="787 808 1112 840">The Antenna position(new).</p> 
<p data-bbox="292 1203 576 1234">Bottom Side(PCB00368)</p> 	<p data-bbox="1006 1203 1291 1234">Bottom Side(PCB00388)</p> 
<p data-bbox="110 1596 1477 1659">On the bottom side, there is a simple movement between the coax connector and 12 pin connector see the change, also removed one hole.</p>	