
# 14. SETUP PHOTOS


### 14.1. ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



Page 410 of 417

### 14.2. RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)

#### 14.2.1. AC UNIT







Page 411 of 417

UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.


#### 14.2.2. POE UNIT







Page 412 of 417


# 14.3. RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)






Page 413 of 417





Page 414 of 417


# 14.4. POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP






UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.


Page 415 of 417





Page 416 of 417

### 14.5. DYNAMIC FREQUENCY SELECTION MEASUREMENT SETUP





# **END OF REPORT**

Page 417 of 417