

May 24, 2009

P.O. Box 370 Newberry, Florida 32669

Timco Engineering, Inc.
849 NW State Road 45

Subject: FCC ID: Q9SHD-1000 Attestation statement that the end user can't tune the transmitter.

Gentlemen;

The equipment meets the requirements of the FCC Rules, Part 90.203(e) and (g), as applicable.

Programming of this product's transmit frequencies can be performed **ONLY** by the manufacturer or by service or maintenance personal. The operator cannot be program transmit frequencies using the equipment's external operation controls.

Northfield Telecommunications, Inc.

A handwritten signature in black ink, appearing to read "Peter", is written over a light blue rectangular background.

Peter/ Vice President