

July 22, 2013

Re: FCC ID: QC8-RDL3000RMF
Applicant: Redline Communications Inc.
Correspondence Reference Number: 44075
Form 731 Confirmation Number: EA143802
Date of Original E-mail: 07/16/2013

Dear Mr. Hardt

Response to the email:

During initial testing of the Controller and Subscriber units, we had difficulty accessing the IP address of the Subscriber unit. We were able to get it running for a brief time, but now the IP address of the Subscriber unit cannot be located at all; hence we are unable to modify any settings or continue testing. Is there any additional documentation or information you could provide to help us resolve this issue?

<rdl>The issue has been resolved during Redline engineer visit at FCC. Please let us know if additional assistance is needed.

Sincerely,



Rod Cronin
Director, Product Management
Ph: 905.479.8344 x2377
rcronin@redlinecommunications.com