

## Appendix C. Test Photo

**Front (5 mm)**



**Rear (5 mm)**



**KCTL Inc.**


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
Tel : 82-31-285-0894 Fax : 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR17-SPF0002


Page (48) of (50)

**KCTL**

**Left (5 mm)**



**Right (5 mm)**



**KCTL Inc.**


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
Tel : 82-31-285-0894 Fax : 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR17-SPF0002

Page (49) of (50)

**KCTL**

**Top (5 mm)**



**Bottom (5 mm)**



**KCTL Inc.**


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
Tel : 82-31-285-0894 Fax : 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR17-SPF0002


Page (50) of (50)

**KCTL**

**System Check 2 450 MHz**



**Liquid Depth MSL 2450**



**- END OF REPORT -**