



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR22-SPF0007
Page (55) of (61)



Appendix C. #Antenna Location & Distance



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR22-SPF0007
Page (56) of (61)



KCTL

Appendix D. EUT Photo

D.1) Front



D.2) Rear



D.3) Left



D.4) Right



D.5) Top




D.6) Bottom




Appendix E. Test Setup Photo


B.1) Body_Front(5 mm)




B.2) Body_Rear(5 mm)



B.3) Body_Left(5 mm)



B.4) Body_Right(5 mm)



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR22-SPF0007
Page (61) of (61)

 eurofins

KCTL

B.5) Body_Top(5 mm)



End of test report