



## 8. SETUP PHOTOS


### RADIATED RF MEASUREMENT SETUP – Laptop Configuration







**RADIATED RF MEASUREMENT SETUP – X Configuration**







**RADIATED RF MEASUREMENT SETUP – Y Configuration**






**RADIATED RF MEASUREMENT SETUP – Z Configuration**







**POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP**





**END OF REPORT**