



190 Mathilda Place, Sunnyvale, CA 94086.

Tel: 408 543 3300, Fax 408 543 3399

We

Broadcom Corporation
190 Mathilda Place
Sunnyvale
California CA 94086 USA
Contact: Mr Daniel Lawless
Tel: +1 408-922-5870
Fax: +1 408-543-3399

Hereby declare under our sole responsibility, that the product

Model Name: Broadcom 802.11g WLAN Mini PCI Card
Model No. BCM94318MPG (FCC ID: QDS-BRCM1016)

To which this declaration relates, has been tested for SAR in the worst case configuration, PP02X WNC antenna.

Dell platforms PP05L, PP07L (PP08L), PP02X and PPT were previously tested with all antennas detailed under this submission with an antenna connector packet power of 15dBm for both DSSS and OFDM transmissions. It was identified as tabulated in the attached data that the PP02X (WNC Main antenna) was the worst configuration for all platform/antenna combinations. This data represents the worst case for measurements on all platform/antenna (Main and Aux) in all lap and bystander test positions measured.

Dell Platform Model #	Antenna Manufacturer	2.4GHz Worst case Measurement position	Worst case 2.4GHz SAR measured W/Kg
PP07L (PP08L)	WNC	Ch11 5mm bystander Main antenna	0.353
	Phycomp	Ch11 5mm bystander Main antenna	0.18
PP02X	Hitachi	Ch1 5mm Bystander Main antenna	0.426
	WNC	Ch6 5mm Bystander Main antenna	0.479
PP05X	WNC	Ch11 5mm bystander Aux antenna	0.148
	Hitachi	Ch6 5mm bystander Main antenna	0.350
PPT	WNC	Ch6 5mm Bystander Main antenna	0.42

March 18, 2005

Daniel Lawless
Manager, Compliance Engineering