

Lucy Tsai

From: Claire Hoque
Sent: Wednesday, May 13, 2009 9:53 AM
To: Lucy Tsai
Cc: Chi Tsou
Subject: answer: 09U12521 TCB questions: Broadcom Corporation, FCC ID: QDS-BRCM1048, Assessment NO.: AN09T9173/9174/9175, Notice#1
Attachments: BCM943225HMB Regulatory User Guide revised 5-12-09.pdf; 09U12521-21A_ FCC ITE Report.pdf

Hi Lucy,

Pls see answer below.
Thanks,

Claire

-----Original Message-----

From: Lucy Tsai
Sent: Tuesday, May 12, 2009 9:21 AM
To: Claire Hoque
Subject: FW: Broadcom Corporation, FCC ID: QDS-BRCM1048, Assessment NO.: AN09T9173/9174/9175, Notice#1

Hi Claire,

Please address following issues.

Q#1: User manual indicated that this module is also supported 5GHz which doesn't agree with this application. Please address.
<answer>manual is revised.

Q#2: There are no information whether the Bluetooth and WLAN devices can transmit simultaneously. Please clarify. If they can transmit simultaneously, EMC co-location test should be conducted because sharing the same antenna.
<answer>WLAN and Bluetooth will NOT transmit simultaneously.

Q#3: Please include FCC ID into Part 15B test report.
<answer>report is revised.

Best Regards,
Lucy

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.