


11. **SETUP PHOTOS**


ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP






RADIATED RF MEASUREMENT SETUP






TEL: (510) 771-1000 This report shall not be reproduced except in full, without the written approval of UL CCS.



TEL: (510) 771-1000 This report shall not be reproduced except in full, without the written approval of UL CCS.

POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





END OF REPORT

Page 79 of 79