
10. SETUP PHOTOS


ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




Page 235 of 238

RADIATED RF MEASUREMENT SETUP






Page 236 of 238




COMPLIANCE CERTIFICATION SERVICES (UL CCS) FORM NO: CCSUP4701F 47173 BENICIA STREET, FREMONT, CA 94538, USA 73 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-08 This report shall not be reproduced except in full, without the written approval of UL CCS. FAX: (510) 661-0888

Page 237 of 238

POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





END OF REPORT

Page 238 of 238

COMPLIANCE CERTIFICATION SERVICES (UL CCS)FORM NO: CCSUP4701F47173 BENICIA STREET, FREMONT, CA 94538, USATEL: (510) 771-1000FAX: (510) 661-0888This report shall not be reproduced except in full, without the written approval of UL CCS.