


INTERTEK TESTING SERVICES

Report No.: HK08011098-1
Model No.: #4874
Sample No.: 2/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Tested By: [Signature]
(Chan Ho Yin)

Date: 22/1/2008

Checked By: [Signature]
([Signature])

Date: 30/1/08

Test Result : Pass / Fail / NA


INTERTEK TESTING SERVICES

Report No.: HK08011098-1

Model No.: #4874

Sample No.: 2/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Tested By: [Signature]
 (Don 16 4m)

Date: 22/1/2008

Checked By: [Signature]
 (Don 16 4m)


Date: 30/1/08

Test Result : Pass / Fail / NA

INTERTEK TESTING SERVICES

Report No.: HK08011098-1
Model No.: #4874
Sample No.: 2/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Tested By: [Signature]
(Chen Ho Yip)

Date: 22/1/2008

Checked By: [Signature]
(Tse Yee Chan)


Date: 30/1/08

Test Result : Pass / Fail / NA

INTERTEK TESTING SERVICES

Report No.: HK08011098-1
Model No.: #4874
Sample No.: 2/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Tested By: [Signature]
(Chan Ho Yip)

Date: 22/1/2008

Checked By: [Signature]
(Tony Chan)

Date: 30/1/08

Test Result : Pass / Fail (NA)