



P/N 1244: Version with WLAN




AWR300-WLAN
p/n 1244 SN 1244002068
FCC ID QG2AWR300 IC: 6252A-AWR300



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.


Contains Transmitter Modules:
FCC ID X3ZBTMOD7 IC:8828A-MOD7
FCC ID X3ZWFMOD9 IC:8828A-MOD9




P07/18

Agriendent GmbH, Steinklippenstr. 10, 30890 Barsinghausen, Germany

P/N 1243: Version without WLAN




AWR300
p/n 1243 SN 1243002525
FCC ID QG2AWR300 IC: 6252A-AWR300



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.


Contains Transmitter Module:
FCC ID X3ZBTMOD7 IC:8828A-MOD7




P07/18

Agriendent GmbH, Steinklippenstr. 10, 30890 Barsinghausen, Germany

P/N 1247: Version with WLAN ('Tepari' branding)




AWR300-WLAN
p/n 1247 SN 1247001051
FCC ID QG2AWR300 IC: 6252A-AWR300



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.

Contains Transmitter Modules:
FCC ID X3ZBTMOD7 IC:8828A-MOD7
FCC ID X3ZWFMOD9 IC:8828A-MOD9



P07/18

Agriendent GmbH, Steinklippenstr. 10, 30890 Barsinghausen, Germany