

Appendix C. Test Photo

Front(Ant.1)



Front(Ant.2)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
Tel : 82-31-285-0894 Fax : 82-505-299-8311
www.kctl.co.kr


Report No.:
KR17-SPF0001-B
Page (87) of (90)

KCTL**Front(Ant.3)**

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
Tel : 82-31-285-0894 Fax : 82-505-299-8311
www.kctl.co.kr



Report No.:
KR17-SPF0001-B
Page (88) of (90)

KCTL**System Check 2 450 MHz****System Check 5 000 MHz**

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
Tel : 82-31-285-0894 Fax : 82-505-299-8311
www.kctl.co.kr



Report No.:
KR17-SPF0001-B
Page (89) of (90)

KCTL**Liquid Depth HSL 2 450****Liquid Depth MSL 2 450**

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
Tel : 82-31-285-0894 Fax : 82-505-299-8311
www.kctl.co.kr

Report No.:
KR17-SPF0001-B
Page (90) of (90)

KCTL**Liquid Depth HSL 5 000****Liquid Depth MSL 5 000**

- END OF REPORT -