

Internal Photos – MIRA HDR



Photo 1: MIRA HDR System




Photo 2: Lid removed, exposing Blockmaster and transmitter and receiver antennas




Photo 3: Lid removed from Blockmaster




Photo 4: MB for Blockmaster – back




Photo 5: MCU – front




Photo 6: MCU – back




Photo 7: Timing generation board – front




Photo 8: Timing generation board – back




Photo 9: Transmitter antenna



HV board

Photo 10: Lid removed, exposing the HV board



Photo 11, HV board – back



Photo 12: Bottom view of transmitter antenna




Photo 13: Antenna assembly removed from antenna





Photo 14: Pulse generator - front



Photo 15: Pulsegenerator – back



Photo 16: Receiver unit



Coax lines from receiving antenna flares

MB for Rx, MCU and ADC board

Coax lines from receiving antenna flares

Photo 17: Lid removed




Photo 18: MB RX board – back

For MCU, see 'Photo 5: MCU – front' and 'Photo 6: MCU – back' on page 4




Photo 19: ADC board – front




Photo 20: ADC board – back



Photo 21: Rx-unit antenna flares




Photo 22: One set of antenna flares removed from antenna