

To: (ATCB) Marianne Bosley, (FCC) George Tannahill  
From: "Timothy R. Johnson" <tjohnson@AmericanTCB.com>  
Subject: FW: Please modify the wrong ID (EPoX Computer Co., Ltd.)  
Cc: (ATCB) Bill Graff - primary, (ATCB) ATCB Taiwan, (ATCB) Dismissal Etc  
Bcc:  
Attached:

George.....

Please have the following dismissed do to a mistyped FCC ID....We are reissuing under FCC ID QLHCAQ0504 today.

To Dismiss:  
ATCB002054 (for internal use)

FCC ID: QLHCA0504  
TC219778

Thank you

Tim

Reply-To: <dward@atcb.com>  
From: "dward ATCB" <dward@atcb.com>  
To: "William Graff" <whgraff@atcb.com>,  
"Timothy R. Johnson" <tjohnson@AmericanTCB.com>  
Subject: FW: Please modify the wrong ID (EPoX Computer Co., Ltd.)  
Date: Thu, 20 Jan 2005 17:27:33 -0800  
X-Mailer: Microsoft Office Outlook, Build 11.0.5510  
Thread-Index: AcT+x6pX2MGss1jPSfCYKIPu1cxjbQAj/AgwAAAbBQA=

X-OriginalArrivalTime: 21 Jan 2005 01:31:14.0250 (UTC) FILETIME=[E54DC2A0:01C4FF58]

Hi Bill / Tim  
Can you dismiss the wrong FCC ID and correct the ID on the above project.  
The applicant would like this done as quickly as possible.

Thanks  
*Dennis Ward*  
*Evaluation Engineer*  
*AmericanTCB*  
*Certification Resource for the Wireless Industry*  
[www.atcb.com](http://www.atcb.com)  
(703) 847-4700  
Direct: (703) 880 4841

*NOTICE: This E-Mail message and any attachment may contain privileged or company proprietary information. If you received this message in error, please return to the sender.*

---

**From:** <\$BDD9cC#>(J [mailto:[major@tradeint.com.tw](mailto:major@tradeint.com.tw)]

**Sent:** Thursday, January 20, 2005 5:24 PM  
**To:** dennis@atcb.com  
**Subject:** FW: Please modify the wrong ID (EPoX Computer Co., Ltd.)  
**Importance:** High

FYI.

Major

-----Original Message-----

**From:** Chen, Elisa (Taipei) [<mailto:Elisa.Chen@sgs.com>]  
**Sent:** Thursday, January 20, 2005 4:12 PM  
**To:** whgraff@atcb.com  
**Cc:** major@atcb.com; Su, Vincent (Taipei)  
**Subject:** Please modify the wrong ID (EPoX Computer Co., Ltd.)  
**Importance:** High

Hi William,

We found the ID Number on the Grant of EPoX Computer Co., Ltd. (ATCB002054) you issued is wrong.  
It should be **QLHCAQ0504** rather than QLHCA0504.  
We checked FCC-\$BIG-(Js website and found the ID is also a wrong one in FCC-\$BIG-(Js file.  
Please modify the ID Number and issue a new Grant for us as soon as possible.  
Thank you very much for your consideration upon this case!

Regards,  
Elisa Chen

---  
Elisa Chen  
E&E Lab. of SGS Taiwan Ltd.  
E-Mail: [elisa.chen@sgs.com](mailto:elisa.chen@sgs.com)  
TEL: +886 2 2299 3279 ext. 1161  
FAX: +886 2 2298 2698  
No. 134, Wu Kung Road, Wuku Industrial Zone,  
Taipei County, Taiwan

---

The information in this email and any attachments is confidential and intended solely for the use of the individual(s) to whom it is addressed or otherwise directed. If you are not a named addressee or otherwise an intended recipient, you are requested to immediately notify the sender and to delete the email and all attachments from your system.

Visit <http://www.sgs.com>

Timothy R. Johnson, NARTE Certified EMC Engineer (No. EMC-002205-NE)  
Examining Engineer  
American TCB, Inc.  
6731 Whittier Ave.  
McLean, VA 22101

email: [tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

alternate email: TRJ@adelphia.net

USA direct number: 404-414-8071 & 678-648-3191

USA corporate phone: 703-847-4700

USA corporate fax: 703-847-6888