



15 December 2008

Re: Tune Up Procedure – FCCID: QRF-FMXLJD35UY

This letter is to inform you that the TR-WMX-3.5-pBS product marketed by Tranzeo Wireless Technologies does not require a tune up procedure in order to ensure compliant operation in it's final installation. This product is tuned and calibrated at the factory, and there are no user serviceable parts or software options that could affect the operating frequency or output power of the device.

For these reasons, no tune-up procedure is included with this submission for FCC certification.

Sincerely,

A handwritten signature in blue ink that reads "Andrew Marles".

Andrew Marles, EMC Manager
Tranzeo Wireless Technologies
19473 Fraser Way
Pitt Meadows, BC V3Y 2V4