

## 2.4GHz Wireless Access Point

The firmware supplied with this unit is specific to Tranzeo Wireless Technologies Inc. and is the latest version of its series. Only pre-approved and supplied upgrades are permitted.

This device complies with part 15 of FCC Rules. Operation is subject to the following conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference that may cause undesired operation.

## TR-6500f

FCC ID: QRF-N621ESYK  
IC: 5181A-N621ESYK  
Manufactured: Oct-24-2007  
Serial Number: TR-65A0CN0231285  
Firmware Version: 3.5.2  
MAC Address: 00:60:B3:3F:83:D1

Tranzeo Wireless Technologies Inc. - Made in Canada



This unit has a built-in amplifier,  
It should not be set higher than  
18.00 dB of Radio power.

*Andrea Manley*

EMC Manager

► HORIZONTAL POLARITY

↑ VERTICAL POLARITY ↑

## 2.4GHz Wireless Access Point

The firmware supplied with this unit is specific to Tranzeo Wireless Technologies Inc. and is the latest version of its series. Only pre-approved and supplied upgrades are permitted.

This device complies with part 15 of FCC Rules. Operation is subject to the following conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference that may cause undesired operation.

# TR-6519f

FCC ID: QRF-N621ESYK  
IC: 5181A-N621ESYK  
Manufactured: Sep-14-2007  
Serial Number: TR-65A0CN0221454  
Firmware Version: 3.5.2  
MAC Address: 00:60:B3:0D:B6:C7

Tranzeo Wireless Technologies Inc. - Made in Canada



This unit has a built-in amplifier,  
It should not be set higher than  
18.00 dB of Radio power.

*Andrea Manley*

EMC Manager