

## ***Change in Identification***

PHOENIX TESTLAB GmbH  
Product Certification  
Königswinkel 10

*Date: June 4, 2010*

D 32825 Blomberg

### **Bluetooth Module / Co-location with RFID Reader**

Dear Sir or Madam,

we apply for change in identification for the grant:

Original FCC ID: ED9LMX9838.  
Original grant date: 02/08/2007.

New FCC ID: QSS-2LMX9838

No modifications were made, the available FCC test results can be used.  
The reason for change in identification is the co-location of a RFID reader with  
FCC ID: QSS-TRM

Thank you for your attention in this matter.

Johann Roidt



TÜV SÜD SENTON GmbH  
EMC Test Laboratory  
Äußere Frühlingstr. 45  
D-94315 Straubing