




CAUTION
K12 Sensor
WATER SENSITIVE TO TEMPERATURE DURING STORAGE
WAFER MAY BE DAMAGED BY STORING OUTSIDE OF RECOMMENDED RANGE
DO NOT STORE WAFER BETWEEN 15°C (59°F) TO 40°C (104°F) AT ALL TIMES. SEE OWNER'S MANUAL

NOTICE
WAFER BREAKAGE HAZARD
Vacuum Bagging May Cause
Wafer Breakage
Do Not Vacuum Bag Shipper



NOTICE
WAFER BREAKAGE HAZARD
Vacuum Bagging May Cause
Wafer Breakage
Do Not Vacuum Bag Shipper


CAUTION
WAFER SENSITIVE TO
TEMPERATURE DURING STORAGE
WAFER MAY BE DAMAGED AND
WARRANTY VOIDED BY STORING
OUTSIDE OF RECOMMENDED
RANGE
STORE WAFER BETWEEN
15C (59F) TO 40C (104F) AT ALL
TIMES. SEE OWNER'S MANUAL



H93-120-1010-1011




KLA Tencor
Accelerating Yield

CAUTION

**WAFER SENSITIVE TO
TEMPERATURE DURING STORAGE**

**WAFER MAY BE DAMAGED AND
WARRANTY VOIDED BY STORING
OUTSIDE OF RECOMMENDED
RANGE**

**STORE WAFER BETWEEN
15C (59F) TO 40C (104F) AT ALL
TIMES. SEE OWNER'S MANUAL.**



0548685-000 AD