



To: Mr. Tim Johnson, American TCB
From: David Waitt, Airespace
Subject: Inquiries regarding Certification application for FCC ID **QTZUSAP1200A**
Date: 24 March 2003

Tim,
Below are the replies to your inquiries regarding this application. The answers are numbered corresponding to your inquiries in your letter dated 24 March 2003. If something is unclear, or if you have additional concerns, please contact me.

Best Regards,

A handwritten signature in black ink, appearing to read "David Waitt".

David Waitt
Consultant representing Airespace

ATCB 1) The BOM contains 2 RF TX Cards. This device only contains 1 TX card. Please explain.

Airespace: This was an error. The BOM for the dual band product containing two cards was inadvertently submitted. The correct BOM has been uploaded to the ATCB site.

ATCB 2) Please provide a schematic for this device. The schematic provided only contained a block diagram.

Airespace: A more detailed schematic has been uploaded to the ATCB site.

ATCB 3) Please provide a users manual for this device. This manual must include appropriate FCC statements and RF exposure information.

Airespace: The manual was accidentally omitted from the original application. It has been uploaded to the ATCB site.