

RE: QW9JC8857RCPC

Attention: Yongpan Sheng

During the review of this device, the following items need to be clarified. Please be aware that there may be additional questions based upon the responses to these items.

- 1. No request for confidentiality was included in the application. Please confirm that confidentiality is not required.
- 2. For measurements below 30 MHz, was the loop antenna rotated about its vertical axis per ANSI C63.4?
- 3. Please show compliance to the bandedge requirement per 15.215(c). This may typically be done by extending the occupied bandwidth plot by at least 1 MHz each direction outside the assigned transmitter frequency band and ensuring use of the correct resolution bandwidth.

Best Regards,

and May

Michael Mobley mmobley@atcb.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to the correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.