


Annex B of test report: F082190E01  
EUT: 2BTHFCK2  
Manufacturer: Peiker acoustic GmbH

---




82190\_1.jpg

EUT, PCB, top view

Annex B of test report: F082190E01  
EUT: 2BTHFCK2  
Manufacturer: Peiker acoustic GmbH


---



82190\_2.jpg

EUT, PCB, bottom view

Annex B of test report: F082190E01  
EUT: 2BTHFCK2  
Manufacturer: Peiker acoustic GmbH




82190\_3.jpg

PCB, top view, shielding chamber 1 cover removed

Annex B of test report: F082190E01  
EUT: 2BTHFCK2  
Manufacturer: Peiker acoustic GmbH


---



82190\_4.jpg

PCB, bottom view, shielding chamber 2 cover removed

Annex B of test report: F082190E01  
EUT: 2BTHFCK2  
Manufacturer: Peiker acoustic GmbH




82190\_5.jpg

Shielding chamber 1

Annex B of test report: F082190E01  
EUT: 2BTHFCK2  
Manufacturer: Peiker acoustic GmbH

---



82190\_6.jpg

Shielding chamber 2