

Enterasys Networks

50 Minuteman Road Andover MA 01810 U.S.A.

Tel: 978-684-1009 Fax: 978-684-1009


Declaration letter

To Whom it may concern,

This applicant would like to filling Class II change (add 5GHz band2) to FCC ID: QXO-OAP36B (2.4GHz & 5GHz band4). It is new equipment class filling so that it couldn't fill Class II change and required a new FCC ID.

FCC ID: QXO-OAP36C (2.4GHz & 5GHz band2 & band4). The all test report in test report (2.4GHz & 5GHz band4:15.247) is same as FCC ID:QXO-OAP36B so that it is just uploaded 5GHz band2 (15.407) report to FCC website.

Sincerely yours,

Applicant's company name : Enterasys Networks
Applicant's company address : 50 Minuteman Road Andover MA 01810 U.S.A.
Signature : 
Job Title and Dept. : John Ballew / Senior Compliance Engineer
E-Mail : jballew@enterasys.com
Tel. : 978-684-1009