



30141_3.jpg BCM001 test board, top view




**PHOENIX
TEST-LAB**

Annex B of test report R30141A Edition 1 Revision 1
EUT: BCM001
Manufacturer: Bury GmbH & Co. KG




30141_4.jpg BCM001 test board, bottom view




Annex B of test report R30141A Edition 1 Revision 1
EUT: BCM001
Manufacturer: Bury GmbH & Co. KG




30141_8.jpg BCM001 W2-1 (with integrated antenna), top view




Annex B of test report R30141A Edition 1 Revision 1
EUT: BCM001
Manufacturer: Bury GmbH & Co. KG




30141_5.jpg BCM001 W2-1 (with integrated antenna), bottom view




Annex B of test report R30141A Edition 1 Revision 1
EUT: BCM001
Manufacturer: Bury GmbH & Co. KG



30141_7.jpg BCM001 W2-3 (with temporary antenna connector), top view



Annex B of test report R30141A Edition 1 Revision 1
EUT: BCM001
Manufacturer: Bury GmbH & Co. KG



30141_6.jpg BCM001 W2-3 (with temporary antenna connector), bottom view