

11734 South Election Drive Suite 200 Draper, Utah 84020 (801) 523-3100

Date: 09/1/2010

To: Federal Communications Commission

445 12th Street, SW Washington, DC 20554

Re: Letter of Changes FCC ID: <u>R33C4HC2001</u>

We are informing the interested parties regarding changes made to the following product model number.

C4-HC200-E-x – New updated model number C4-HC200B-E-x (x denotes the color of the unit)

Changes in RF section of the product are:

=~1a~

- 1) Additional filtering added to the DC power supply that supplies the RF radio circuitry.
- 2) RF output balun component value change to improve RF signal integrity.
- 3) 2 additional PCB ground layers added.

Thank you,

Ajit Sampalli

Compliance Engineer

Control4 Technologies