



SCHWEITZER ENGINEERING LABORATORIES, INC.

2350 NE Hopkins Court • Pullman, WA 99163-5603 USA

Phone: 509.332.1890 • Fax: 509.332.7990

www.selinc.com • info@selinc.com

Request for Confidentiality Letter for the SEL-8300 Wireless Interface Faulted
Circuit Indicator Reader

March 1, 2007

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, Maryland 21046

To whom it may concern,

We hereby respectfully request that under the provision of 47 CFR 0.459, the documents listed below and attached with this application for certification be provided with confidential status.

- Schematics.pdf
- Theory of Operation.pdf
- Frequency Block Diagrams.pdf

Any exhibit / information for which we have requested confidentiality, but which may not be accorded such treatment by the FCC, should be returned to us.

The documents listed above contain trade secrets that are treated as confidential by us. Substantial competitive harm to us could result should they be made available to the public.

Additionally, we request that the following exhibits be held temporarily confidential in accordance with public notice DA 04-1705.

- Internal photos.pdf
- External photos.pdf
- Antenna.pdf

Sincerely,

A handwritten signature in cursive script that reads "Don MacArthur".

Don MacArthur
Compliance Engineer
Schweitzer Engineering Laboratories, Inc.
2350 NE Hopkins Court
Pullman, WA 99163