

NORTHWEST EMC, INC.

22975 NW Evergreen Parkway, Suite 400
Hillsboro, OR 97124

March 14, 2007

Dear Application Examiner:

A problem was identified with the RF Exposure exhibit for FCCID: R34SEL-8300.
The verbiage needed to be edited to remove one statement.

We would like to submit a revised RF Exposure exhibit to supersede the current
one on file.

Best regards,

Northwest EMC, Inc.