





Band38-15MHz-QPSK-37825-75RB#0

Band38-15MHz-16QAM-37825-75RB#0




Band38-15MHz-QPSK-38000-75RB#0

Band38-15MHz-16QAM-38000-75RB#0




Band38-15MHz-QPSK-38175-75RB#0


Band38-15MHz-16QAM-38175-75RB#0




Band38-15MHz-64QAM-37825-75RB#0




Band38-20MHz-QPSK-37850-100RB#0




Band38-15MHz-64QAM-38000-75RB#0





Band38-20MHz-QPSK-38000-100RB#0



Band38-15MHz-64QAM-38175-75RB#0





Band38-20MHz-QPSK-38150-100RB#0





Band38-20MHz-16QAM-37850-100RB#0

Band38-20MHz-64QAM-37850-100RB#0



Band38-20MHz-16QAM-38000-100RB#0


Band38-20MHz-64QAM-38000-100RB#0




Band38-20MHz-16QAM-38150-100RB#0

Band38-20MHz-64QAM-38150-100RB#0

Band41-5MHz-QPSK-39675-25RB#0




01:38:41 04.01.2023




01:39:04 04.01.2023

Band41-5MHz-16QAM-40620-25RB#0




01:39:54 04.01.2023

Band41-5MHz-QPSK-40620-25RB#0




01:39:31 04.01.2023

Band41-5MHz-16QAM-41565-25RB#0



01:40:47 04.01.2023


Band41-5MHz-QPSK-41565-25RB#0



01:40:22 04.01.2023

Band41-5MHz-16QAM-39675-25RB#0

Band41-5MHz-64QAM-39675-25RB#0




07:22:03 04.01.2023




01:52:03 04.01.2023

Band41-10MHz-QPSK-40090-50RB#0

Band41-5MHz-64QAM-40620-25RB#0




07:22:29 04.01.2023




01:44:20 04.01.2023

Band41-10MHz-QPSK-40290-50RB#0

Band41-5MHz-64QAM-41565-25RB#0




07:22:54 04.01.2023




03:31:20 04.01.2023

Band41-10MHz-QPSK-39700-50RB#0

Band41-10MHz-QPSK-40620-50RB#0




01:52:39 04.01.2023




03:32:32 04.01.2023

Band41-10MHz-QPSK-41540-50RB#0

Band41-10MHz-QPSK-40640-50RB#0




01:44:54 04.01.2023



01:53:14 04.01.2023

Band41-10MHz-16QAM-39700-50RB#0

Band41-10MHz-QPSK-40740-50RB#0



03:31:54 04.01.2023




01:52:23 04.01.2023

Band41-10MHz-QPSK-41190-50RB#0


Band41-10MHz-16QAM-40090-50RB#0




Band41-10MHz-16QAM-40290-50RB#0




Band41-10MHz-16QAM-40620-50RB#0




Band41-10MHz-16QAM-40640-50RB#0




Band41-10MHz-16QAM-40740-50RB#0




Band41-10MHz-16QAM-41190-50RB#0



Band41-10MHz-16QAM-41540-50RB#0




01:53:34 04.01.2023




07:25:19 04.01.2023

Band41-10MHz-64QAM-40620-50RB#0




07:17:42 04.01.2023



07:18:00 04.01.2023

Band41-10MHz-64QAM-40640-50RB#0




07:20:31 04.01.2023




07:20:50 04.01.2023

Band41-10MHz-64QAM-40290-50RB#0

Band41-10MHz-64QAM-40740-50RB#0




07:25:37 04.01.2023




01:41:37 04.01.2023

Band41-15MHz-QPSK-40620-75RB#0

Band41-10MHz-64QAM-41190-50RB#0




07:28:54 04.01.2023




01:42:14 04.01.2023

Band41-15MHz-QPSK-41190-75RB#0

Band41-10MHz-64QAM-41540-50RB#0





07:18:19 04.01.2023





01:42:53 04.01.2023

Band41-15MHz-QPSK-39725-75RB#0



Band41-15MHz-16QAM-39725-75RB#0



Band41-15MHz-64QAM-40620-75RB#0




Band41-15MHz-64QAM-41515-75RB#0




Band41-15MHz-64QAM-39725-75RB#0

Band41-20MHz-QPSK-39750-100RB#0




01:49:41 04.01.2023




01:50:18 04.01.2023

Band41-20MHz-QPSK-40640-100RB#0




01:47:19 04.01.2023




01:47:55 04.01.2023

Band41-20MHz-QPSK-40740-100RB#0





03:33:40 04.01.2023



03:34:14 04.01.2023



Band41-20MHz-QPSK-40620-100RB#0

Band41-20MHz-QPSK-41140-100RB#0




Band41-20MHz-16QAM-40340-100RB#0

Band41-20MHz-QPSK-41490-100RB#0





Band41-20MHz-16QAM-40620-100RB#0

Band41-20MHz-16QAM-39750-100RB#0





Band41-20MHz-16QAM-40140-100RB#0

Band41-20MHz-16QAM-40640-100RB#0





Band41-20MHz-64QAM-39750-100RB#0

Band41-20MHz-16QAM-40740-100RB#0




Band41-20MHz-64QAM-40140-100RB#0

Band41-20MHz-16QAM-41140-100RB#0



Band41-20MHz-16QAM-41490-100RB#0

Band41-20MHz-64QAM-40340-100RB#0




07:19:09 04.01.2023

Band41-20MHz-64QAM-40740-100RB#0




07:19:27 04.01.2023

Band41-20MHz-64QAM-40620-100RB#0



07:27:08 04.01.2023

Band41-20MHz-64QAM-41140-100RB#0




07:19:48 04.01.2023

Band41-20MHz-64QAM-40640-100RB#0



07:16:19 04.01.2023


Band41-20MHz-64QAM-41490-100RB#0




07:27:27 04.01.2023


10. APPENDIX D: CONDUCTED BAND EDGE

Test Graphs:
GSM:







GSM1900-512-0




GPRS1900-810-0




GSM1900-810-0



EGPRS1900-512-2



GPRS1900-512-0



EGPRS1900-810-2