

LABEL AND LOCATION

WHEN YOU NEED TO BE SURE





FCC ID: RAB-IPDL-WT1
 This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation



Itron
 IntelliPEAK DirectLink IPDL-W1

↑ THIS WAY UP
 YELLOW ON NETWORK ON
 RED ON RELAY 1
 GREEN ON TEST ON

ENERGY MANAGEMENT EQUIPMENT Listed Conforms to UL STD 916 RAIN-TIGHT ENCLOSURE
 Intertek 4009929

FCC Label

CAUTION: RISK OF ELECTRICAL SHOCK. THIS CONTROLLER IS NOT A DISCONNECT. POWER TO THE CONTROLLED APPLIANCE MAY BE AUTOMATICALLY RESTORED AT ANY TIME. ONE OR MORE DISCONNECTS MUST BE OPENED BEFORE SERVICING CONTROLLER OR APPLIANCE.

DATE MFD: 17 18 19 20 21 22
JFMAMJJASOND
 ASSEMBLED IN MEXICO LBL-000014