

September 08, 2014

Federal Communications Commission EQUIPMENT AUTHORIZATION BRANCH 7435 Oakland Mills Road Columbia, MD 21046

Reference: FCC: RAR80005111

The products under this FCC ID have no access to 5600 – 5650 MHz band.

And the device drivers that set the DFS parameters are embedded into the SW load build and not accessible to any user, so the device has no option to change the DFS parameters.

Sincerely,

Marceletenin

Marcel Chenier , Head of R&D Wi-Fi Products, LW Ericsson WiFi Inc 6300 Legacy Drive Plano, Texas 75024 Phone: 1 972 583 0000