
# Appendix C. Set up Photograph Conducted Emission

Mode 1



**FRONT VIEW** 



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C5 Issued Date : Jun. 01, 2005

Report No.: FR542927





SIDE VIEW

Mode 2




FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C5 Issued Date : Jun. 01, 2005





**REAR VIEW** 




SIDE VIEW

# SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C5 Issued Date : Jun. 01, 2005



# Radiation Emission Antenna A



**FRONT VIEW** 




**REAR VIEW** 

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C5 Issued Date : Jun. 01, 2005



# Antenna B



**FRONT VIEW** 



**REAR VIEW** 

# SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C5 of C5 Issued Date : Jun. 01, 2005