



FCC ID Label Format and Location

- Label Placement Location (Back Side of EUT)



- FCC Label Format

FCC Label Placement Location

	<b>Westinghouse®</b>	<b>HOUSEHOLD MICROWAVE OVEN</b>	
MODEL NO. :		MANUFACTURED :	<b>LISTED</b> 49DT E236180
<input type="text" value="Serial Number"/>			
INPUT 120 V AC, 10 A, 60 Hz OUTPUT 2450 MHz			
DISTRIBUTED BY: Salton, Inc., LAKE FOREST, IL 60045			
THIS PRODUCT COMPLIES WITH DHHS RULES 21 CFR SUBCHAPTER J.			
THIS DEVICE COMPLIES WITH PART 18 OF THE FCC RULES.			
<input type="text" value="FCC: RBJ-TSKM1702"/>		MADE IN CHINA (TKL)	
<b>NOT FOR BUILT-IN INSTALLATION</b>			
WARNING – CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL – DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: FAN MOTOR, TURNTABLE MOTOR, OR TIMER MOTOR ASSEMBLY.			
WARNING – RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS.			
WARNING – TO PROVIDE CONTINUED PROTECTION AGAINST ELECTRIC SHOCK, CONNECT TO PROPERLY GROUNDED OUTLETS ONLY. DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF OUTER ENCLOSURE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS.			
CAUTION – THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.			