



PHILIPS

Philips Electronics Singapore Pte Ltd

Attention: Reviewing Engineer
 Federal Communications Commission
 7435 Oakland Mills Road
 Columbia, MD 21046


RE: DECLARATION OF ANTENNA USED IN RC1704701/00RF FCC ID: RCSRC1704701

The PCB Loop antenna used in the RC1704701/00RF is connected to the main PCB via a PCB Trace.

The antenna cannot be removed or replaced by user without taking the whole unit apart, and removing the printed circuits boards from the housing. In the course of doing that, it will void the service warranty provided by manufacturer, and might damage the unit if not careful.

It has a loss of 8 dBi.

Sincerely,


Karl Reynders, General Manager,
Business Line Remote Control
Philips Electronics Singapore Pte Ltd -
Remote Control Systems

620A Lorong 1 Toa Payoh
Building TP1, Level 2,
Singapore 319762
Telephone: (65) 68823000
Fax : (65) 62541691