



PHILIPS

Philips Electronics Singapore Pte Ltd

To : Federal Communications Commission
Equipment Approval Service

Attn: Authorization and Evaluation Division


Reference: FCC ID: **RCSRC1984720**

Jan. 2, 2008

To Whom It May Concern:

We are applying for a Class II permissive change for FCC ID: **RCSRC1984720**. The following are the changes made

* Changes on PWB – Added Pads for additional two capacitors to improve the Frequency response of the RF transmitter (to centralize the carrier frequency & preventing it from drifting too much from set to set).




620A Lorong 1 Toa Payoh
Building TP1, Level 2,
Singapore 319762
Telephone: (65) 68823000
Fax : (65) 62541691



PHILIPS

Philips Electronics Singapore Pte Ltd



Two Pad added for two capacitor , to improve the Frequency stability

Sincerely,

Name: Mr Yeoh Choong Ling
Position : RF Architect
Philips Electronics Singapore Ptd. Ltd.

1/1/08
Date

620A Lorong 1 Toa Payoh
Building TP1, Level 2,
Singapore 319762
Telephone: (65) 68823000
Fax : (65) 62541691