

INTERTEK TESTING SERVICES

hp

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement

Report No.: 0421787
Model No.: 13000


REF -30.0 dBm

AT 10 dB

MKR 31.500 msec

-.26 dB

PEAK
LOG
10
dB/



WA SB
SC FS
CORR

Tested By: *[Signature]*
(Tang)

Date: 26-11-04

Checked By: *[Signature]*

(Jean Ting)

Date: 9/12

Test Result: Pass / Fail / NA

CENTER 49.860 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 100 msec

INTERTEK TESTING SERVICES

hp

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

MKR 31.500 msec

Report No.: 0421787
Model No.: 13000

REF -30.0 dBm

AT 10 dB


- .16 dB

PEAK

LOG

10

dB/



WA SB
SC FS
CORR

Tested By: (Signature)
(Name)

Date: 26-11-04

Checked By: (Signature)
(Name)

Date: 4/12

Test Result : Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 50.0 msec

INTERTEK TESTING SERVICES

hp

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

MKR 1.5000 msec


Report No.: C421784
Model No.: 13000

REF -30.0 dBm

AT 10 dB

- .35 dB

PEAK
LOG
10
dB/



WA SB
SC FS
CORR

Tested By: [Signature]
(26/11/04)

Date: 26-11-04

Checked By: [Signature]
(Ivan Wang)

Date: 1/12

Test Result: Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 50.0 msec

hp

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement

MKR 500.00 μ sec


Report No.: 0421787
Model No.: 13000

REF -30.0 dBm

AT 10 dB

- .14 dB

PEAK
LOG
10
dB/



WA SB
SC FS
CORR

Tested By: *[Signature]*
(7/11/02)

Date: 26-11-02

Checked By: *[Signature]*
(1/12)

Date: **Ivan Wong**

Test Result : Pass / Fail / **NA**

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 50.0 msec