


NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID6\_N/A  
\_0.009\_0.15\_#1

NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID6\_N/A  
\_0.15\_30\_#1


NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID6\_N/A  
\_30\_1000\_#1

NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID6\_N/A  
\_1000\_6000\_#1


NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID6\_N/A  
\_6000\_18000\_#1




NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID6\_N/A  
\_18000\_40000\_#1



NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID16\_N/  
A\_0.009\_0.15\_#1



NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID16\_N/  
A\_0.15\_30\_#1



NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID16\_N/  
A\_30\_1000\_#1




NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID16\_N/  
A\_1000\_6000\_#1






NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID16\_N/  
A\_6000\_18000\_#1


NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID16\_N/  
A\_18000\_40000\_#1




NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID17\_N/  
A\_0.009\_0.15\_#1



NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID17\_N/  
A\_0.15\_30\_#1




NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID17\_N/  
A\_0.0300\_1.0000\_#1



NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID17\_N/  
A\_1.0000\_6.0000\_#1







NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID18\_N/  
A\_30\_1000\_#1

NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID18\_N/  
A\_1000\_6000\_#1

NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID18\_N/  
A\_6000\_18000\_#1

NTNV\_N78-3700-3800\_PC2\_30\_50\_M\_TID18\_N/  
A\_18000\_40000\_#1






NTNV\_N78-3700-3800\_PC2\_30\_50\_H\_TID5\_N/A  
\_0.009\_0.15\_#1


NTNV\_N78-3700-3800\_PC2\_30\_50\_H\_TID5\_N/A  
\_0.15\_30\_#1

NTNV\_N78-3700-3800\_PC2\_30\_50\_H\_TID5\_N/A  
\_30\_1000\_#1


NTNV\_N78-3700-3800\_PC2\_30\_50\_H\_TID5\_N/A  
\_1000\_6000\_#1









NTNV\_N78-3700-3800\_PC2\_30\_50\_H\_TID6\_N/A  
\_6000\_18000\_#1





NTNV\_N78-3700-3800\_PC2\_30\_50\_H\_TID6\_N/A  
\_18000\_40000\_#1




NTNV\_N78-3700-3800\_PC2\_30\_50\_H\_TID16\_N/  
A\_0.009\_0.15\_#1



NTNV\_N78-3700-3800\_PC2\_30\_50\_H\_TID16\_N/  
A\_0.15\_30\_#1











NTNV\_N78-3700-3800\_PC2\_30\_50\_H\_TID17\_N/  
A\_30\_1000\_#1


NTNV\_N78-3700-3800\_PC2\_30\_50\_H\_TID17\_N/  
A\_1000\_6000\_#1




NTNV\_N78-3700-3800\_PC2\_30\_50\_H\_TID17\_N/  
A\_6000\_18000\_#1

NTNV\_N78-3700-3800\_PC2\_30\_50\_H\_TID17\_N/  
A\_18000\_40000\_#1








NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID4\_N/A  
\_0.009\_0.15\_#1

NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID4\_N/A  
\_0.15\_30\_#1


NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID4\_N/A  
\_30\_1000\_#1

NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID4\_N/A  
\_1000\_6000\_#1


NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID4\_N/A  
\_6000\_18000\_#1




NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID4\_N/A  
\_18000\_40000\_#1



NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID5\_N/A  
\_0.009\_0.15\_#1




NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID5\_N/A  
\_0.15\_30\_#1




NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID5\_N/A  
\_30\_1000\_#1

NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID5\_N/A  
\_1000\_6000\_#1




NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID5\_N/A  
\_6000\_18000\_#1

NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID5\_N/A  
\_18000\_40000\_#1



NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID6\_N/A  
\_0.009\_0.15\_#1



NTNV\_N78-3700-3800\_PC2\_30\_60\_L\_TID6\_N/A  
\_0.15\_30\_#1

