



**R.V.R. USA LLC**

7782 NV 46 ST. MIAMI, FL 33166 - USA

Tel: 305-471-9091 | Fax: 305-471-6979 | E-mail: info@rvrusa.com

---

Miami, FL - USA

09/19/19

To Whom It May Concern at:

**FCC - FEDERAL COMMUNICATIONS COMMISSION**  
**Authorization and Evaluation Division**

**Declaration on our FM Transmitter: TEX502LCD and TEX702LCD**

Dear Sir or Madam,

**R.V.R. USA** with **Grantee's FCC Registration Number (FRN): 0009562489**

is located in USA at 7782 NW 46 Street in Miami - FL 33166.


We're submitting our application for two transmitter's certification: TEX502LCD and TEX702LCD under the same FCC ID: **RHDTEX-702LCD** .

This letter is intended to declare that both models are electronically and mechanically identical.

The unique difference is in the RF Power Output.

The output power on the TEX502LCD FM transmitter is locked by firmware (not changeable from the end-user on the panel or via software) and blocking the power supply capacity.

Regards,

  
Andres Serrano  
Manager