


Test report no..: 2_3395-01-01/03

Issue Date: 2003-09-25

Page 56 (64)

Test site






Test report no..: 2_3395-01-01/03

Issue Date: 2003-09-25

Page 57 (64)

Test site





Test report no..: 2_3395-01-01/03

Issue Date: 2003-09-25

Page 58 (64)

Test site






Test report no..: 2_3395-01-01/03

Issue Date: 2003-09-25

Page 59 (64)





Test report no..: 2_3395-01-01/03

Issue Date: 2003-09-25

Page 60 (64)






Test report no..: 2_3395-01-01/03

Issue Date: 2003-09-25

Page 61 (64)






Test report no..: 2_3395-01-01/03

Issue Date: 2003-09-25

Page 62 (64)






Test report no..: 2_3395-01-01/03

Issue Date: 2003-09-25

Page 63 (64)





Test report no..: 2_3395-01-01/03

Issue Date: 2003-09-25

Page 64 (64)

Photographs of the equipment

Antenna we used for radiated measurements (KATHREIN 80010147, 2 dBi gain)

