
1.1. Photographs of Conducted Powerline Test Configuration

• The photographs show the configuration that generates the maximum emission.




FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL : 886-2-2696-2468 FAX : 886-2-2696-2255



SIDE VIEW

SPORTON International Inc. TEL : 886-2-2696-2468 FAX : 886-2-2696-2255
 FCC ID
 : RIW-ZWX-G250

 Page No.
 : 2 of 3


 Issued
 : Nov, 07, 2003

1.2. Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL : 886-2-2696-2468 FAX : 886-2-2696-2255