
# **APPENDIX C. Photographs of Setup**


### **Photographs of Conducted Emission Test Configuration**

FRONT VIEW



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

#### **REAR VIEW**



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C5
Issued Date : July 26, 2004


#### SIDE VIEW



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C5
Issued Date : July 26, 2004


## **Photographs of Radiated Emission Test Configuration**

FRONT VIEW



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C5 Issued Date : July 26, 2004

#### **REAR VIEW**



#### SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C5 of C5 Issued Date : July 26, 2004