



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 19, 2003

RE: Tekkeon

FCC ID: RJ6ET1000S

I have a few comments on the above referenced Application.

- 1) Only one of the users manuals provided was updated for the missing the statements required by 15.21. Please correct both manuals.
- 2) Note that Run #3 has labeled all channels as LOW. This likely should have been LOW, MIDDLE, and HIGH.
- 3) Has the antenna of this device been quantified for gain as 0 dBi? If not, please provide additional information using the substitution method to support the power measurements provided.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.