

Test setup photos of MH BTS ON BT WW

1. Conducted Emission Test setup

Connect to PC Mode



2. Radiated Emission Test (Blow 1GHz)

On Mode



3. Radiated Emission Test (Above 1GHz)

On Mode

