



**AmbiCom Technology, Inc.**

Address: 4F, No.6, Lane 345, Yangguang St.,  
Nei Hu Dist., Taipei 114 Taiwan  
Phone: 886-2-26271758 Ext. 301  
Fax: 886-2-26271757

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Attention: Application Examiner/ Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: RK3BT-GPS

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by AmbiCom Technology, Inc. will establish a new FCC ID under RK3BT-GPS grantee code for purpose of marketing. The original grant to Leadtek Research Inc. FCC ID: I2ILR9537C ). will remain in effect.

An authorization letter by Leadtek Research Inc. is attached.

Per 2.933(b)

1. The original identification is FCC ID: I2ILR9537C
2. The original grant date is 12/11/2003
3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter  
External Photos  
FCC ID label format and location

Sincerely,

Mr. Denny Hsu

Products Manager

AmbiCom Technology, Inc.