

Annex B



This test report annex is electronically signed and valid without handwriting signature. For verification of the electronic signatures, the public keys can be requested at the testing laboratory.

Test report annex authorized:

Thomas Vogler
Lab Manager
Radio Communications & EMC

1 Internal Photos

Refer to Customer documentation!

5040A SBU




Mainboard Front



Mainboard Back



PSU Front




PSU Back


5016A HLD



HLD Internal



Diplexer Bottom




Diplexer Top



Diplexer Connectors



PA Top



PA Bottom

2 Document history

Version	Applied changes	Date of release
	Initial release	2021-04-29