

# Bling Networks Inc.

140 Renfrew Drive Suite 200 Markham, L3R 6B3 Canada

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: MXF-WLTGG1334846

Date: 2021/9/1

To The Commission:

This Change of Identification request applies for a new FCC ID: **ROR1003** as established in 47CFR 2.933(b) for a currently approved device. This application by Blinq Wireless Inc. will establish a new FCC ID under **Bling Networks Inc.** grantee code for purpose of marketing. The original grant to Gemtek Technology Co., Ltd. will remain in effect.

An authorization letter by Gemtek Technology Co., Ltd. is attached.

Per 2.933(b)

1. The original identification is MXF-WLTGG1334846
2. The original grant date is **08/31/2021**.
3. The equipment is electrically, cosmetically and construction identical. Only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.


The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely yours,



---

**Jim Dickerman** / Vice President, Engineering  
**Bling Networks Inc.**

Tel: 416-214-4204

E-mail: [jim.dickerman@blinqnetworks.com](mailto:jim.dickerman@blinqnetworks.com)