

SUBJECT: Variation in module power levels

FCC ID: ROSTEMPUS-1

2 March 2010

To Whom It May Concern:

It should be noted that the measured RF power level detailed in RFI test reports do not match the measured power level detailed on the original test reports/FCC grants for the GSM, Wireless LAN and Bluetooth modules.

Original testing was performed with the modules being tested on a standalone basis and not situated inside a host unit. The measured RF power levels detailed in RFI's test reports were obtained with the respective modules integrated within the TempusIC.

The shielding of the enclosure of the TempusIC product therefore accounts for the reduced power levels detailed in RFI reports.

Respectfully



Chris Hannan

Regulatory Affairs and Operations Manager

Registered Office:

Remote Diagnostic Technologies Ltd

The Old Coach House, The Avenue, Farleigh Wallop, Hampshire, RG25 2HT, UK

Registered in England No. 3321782 VAT No. 692 9012 19 LLC No. 4148022

T +44 (0) 1256 362 400

F +44 (0) 1256 362 415

www.rdtltd.com

info@rdtltd.com