

## ATTESTATION STATEMENT

### Power Level Difference

04/02/2013

**SUBJECT:** Variation in module power levels  
**FCC ID:** ROSTEMPUSIC-2

**TO WHOM IT MAY CONCERN**

It should be noted that the measured RF power levels detailed in the UL RFI test report do not match the measured power levels detailed on the original test report and FCC grant for the GSM module.

Original testing was performed with the module being tested on a standalone basis and not situated inside a host unit. The measured RF power levels detailed in UL RFI's test report were obtained with the GSM module integrated within the Tempus IC.

The shielding of the enclosure of the Tempus IC product therefore accounts for the reduced power levels detailed in the UL RFI report.

Yours sincerely



Chris Hannan  
Programme & Regulatory Affairs Director

Registered office:

Remote Diagnostic Technologies Ltd  
The Old Coach House, The Avenue, Farleigh Wallop, Hampshire, RG25 2HT, UK  
Registered in England No 3321782 VAT No 692 9012 19 LLC No 4148022

T +44 (0) 1256 362 400

F +44 (0) 1256 362 415

[www.rdtltd.com](http://www.rdtltd.com)

info@rdtltd.com