

**XM Satellite Radio Inc Additional Information**  
**Provided in Response to ATCB Questions 1-6 dated June 16, 2008**  
**FCC ID RS2XMPCAR1**  
**June 18, 2008**

- 1) IC labeling requires information regarding the model number as being listed.  
Currently this does not appear to be provided. Please review.  
**The new FCC/IC label reflecting the model number has been uploaded.**
- 2) FYI....Any status to report on the FCC's pre-sample audit test?  
**Yes, the tests are being conducted at the moment. I've already forwarded the response they had to this same question on 06/17/08 to your mail inbox. I'll also let you know as soon as a testing conclusion is made.**
- 3) FYI....Test report uploaded but marked as temp confidential. Kindly note that test reports may not be held as confidential at all.  
**Ok.**
- 4) Test report (15B) should remove test photos since temp confidentiality can not be granted.  
**The test photos concatenated to the (15B) test report has been removed. The updated test report file ending with "rev2" has been uploaded.**
- 5) For < 1 GHz tests, were only dipole antennas used? The equipment list did not appear to show any broadband antennas in the equipment list.  
**Broadband antennas were used only during the unintentional tests i.e. 15.239. The equipment list for both test reports with file names ending with "rev2" have been updated and uploaded.**
- 6) Test report does not appear to confirm if the maximum audio drive output was set to maximum ask given in the KDB information. Please confirm.  
**All tests were carried out at maximum audio drive outputs. It states that at the end of each first paragraph of each configuration test setup description i.e. reports (15B) & (15.239).**