



INTERTEK TESTING SERVICE

Report No.: 17111150HKG-001 (FCC)
17111150HKG-002 (IC)

Equipment Photographs

Model : E1929

(Internal)



FCC ID: RS4-E1929
IC: 4502A-E1929


INTERTEK TESTING SERVICE

Report No.: 1711150HKG-001 (FCC)
1711150HKG-002 (IC)

Equipment Photographs

Model : E1929

(Internal)



FCC ID: RS4-E1929
IC: 4502A-E1929


INTERTEK TESTING SERVICE

Report No.: 1711150HKG-001 (FCC)
1711150HKG-002 (IC)

Equipment Photographs

Model : E1929

(Internal)



FCC ID: RS4-E1929
IC: 4502A-E1929


INTERTEK TESTING SERVICE

Report No.: 17111150HKG-001 (FCC)
17111150HKG-002 (IC)

Equipment Photographs

Model : E1929

(Internal)



FCC ID: RS4-E1929
IC: 4502A-E1929

INTERTEK TESTING SERVICE

Report No.: 17111150HKG-001 (FCC)
17111150HKG-002 (IC)

Equipment Photographs

Model : E1929

(Internal)



FCC ID: RS4-E1929
IC: 4502A-E1929